



We Connect The World



Firmware Release Note

Date: 21 Aug. 2014

Model: WAP-3150NP

Previous Version: V1.0.14

Newly Version: V1.0.15

*****Attention: please read it carefully before you upgrade the firmware.**

1. Please back up your system configuration prior to the upgrade in case any system errors occur.

| | | |
|---------|--------------|---|
| V1.0.5 | 25 Dec. 2013 | 1. Resolve WDS can't work issue when VLAN enabled. |
| V1.0.6 | 14 Jan. 2014 | 1. Resolve UPNP show vendor issue |
| V1.0.8 | 7 Apr. 2014 | 1. Resolve video stream can't work in WDS mode |
| V1.0.9 | 10 June 2014 | 1. Resolve DHCP Server can't save issue in AP Router mode when user use Setup Wizard 2. Resolve VAP List display issue when VAP0 enable WDS with AES encryption 3. Add Auto Reboot function in Management page 4. Add Router AP mode |
| V1.0.10 | 10 July 2014 | 1. Resolve Parental control can't work with time policy |
| V1.0.11 | 21 July 2014 | 1. Resolve 150M bit rate can't work issue |
| V1.0.12 | 29 July 2014 | 1. Resolve Repeater AP's ESSID wrong display in Traffic Monitor page |
| V1.0.13 | 4 Aug. 2014 | 1. Resolve Client Isolation issue 2. Resolve wifi schedule issue in repeater AP mode |
| V1.0.14 | 10 Aug. 2014 | 1. Resolve kernel module issue |
| V1.0.15 | 21 Aug. 2014 | 1. Hardware watchdog enabled |