



*We Connect The World*



## Firmware Release Note

Date: 27 July 2012

Model: WAS-854NP

Previous Version: V1.1.4

Newly Version: V1.1.5

**\*\*\*Attention: please read it carefully before you upgrade the firmware.**

1. Please back up your system configuration prior to the upgrade in case any system errors occur.

V1.0.6	6 Apr. 2011	1. Change 『Group Key Update Period』 and 『Master Key Update Period』 setting range from 10-99999999 to 0-99999999 2. Fixed throughput box issue on status page for IE9
V1.0.7	4 May 2011	1. Fixed WDS's Description can't save problem on WDS Mode 2. Add alert message on WDS Setup page on WDS Mode, when the Channel is 『Auto』 3. Remove Auto Channel option on WDS Mode 4. When operating mode change from AP Mode to WDS Mode, the Channel will change from 『Auto』 to 『6』 5. Change time out on WDS connection
V1.1.0	5 Oct. 2011	1. Fixed Txpower issue
V1.1.1	9 Nov. 2011	1. When Controller send empty ESSID and Host Name to AP, the AP will use original setting
V1.1.2	23 Dec. 2011	1. Fixed Wireless can't connect to AP, when admin enable 1-4 WDS and set Maximum Client to 1-4 on VAP page 2. Add VLAN tag over WDS via VAP 3. Add VLAN setting page and change VLAN setting on VAP settings 4. Change IAPP GUI setting, IAPP only support WPA2 encryption
V1.1.3	13 April 2012	1. Add “Connect Time” and “TX/RX Bytes” information on Associated Clients Status page 2. Support AP Management by WMS-308N FW V1.0.1
V1.1.4	22 May 2012	1. Add Noise information on AP List 2. Adjust discovery mechanism for AP Management

		3. Fixed the device can't connected via wired when VAP enable VLAN tag
V1.1.5	27 July 2012	1. Change ACL log on Event Log page when system receive ACL control message from AP management 2. Add auto disconnect when system receive the block message of ACL from AP management